



NOTICE to MARINERS

NO: 3/2025

LERWICK HARBOUR – VICTORIA PIER MOORING BUOY

Mariners are advised that the mooring buoy north of Victoria Pier has been removed for maintenance purposes.

Mooring Buoy detail:

60°09.328'N, 1°08.489'W
Light - Fl (4) Y 12s

Maintenance is expected to take up to one month to complete.

Mariners are advised whilst buoy is out of the water that vessels mooring on Victoria Pier east can use the mooring bollards on the quay only.

Mariners navigating into Victoria Pier west & north, Albert Wharf and the Spur Jetty are to be aware that the light and buoy are not present.

24 February 2025

Captain Alexander M. Simpson
Harbourmaster